



1/19





Fig. 1



2/19





Fig. 2





4/19





Fig. 4




5/19






6/19


*Fig. 6a*




*Fig. 6b*




*Fig. 6c*



*Fig. 6d*




*Fig. 6e*





7/19



*Fig. 7*

8/19




Fig. 8





9/19





Fig. 9



10/19




Fig. 10

11/19





Fig. 11

**Fig. 12**




13/19


*Fig. 13a*




*Fig. 13b*




*Fig. 13c*




*Fig. 13d*



*Fig. 13e*





14/19




Fig. 14a





Fig. 14b




15/19


**Fig. 15a** UNDERLYING FILM DEPOSITION



**Fig. 15b** FIRST METAL FILM DEPOSITION




**Fig. 15c** PATTERNING OF FIRST METAL FILM



**Fig. 15d** FORMATION OF INSULATING FILM BY ANODIC OXIDATION




**Fig. 15e** ISOLATION OF ELEMENTS






16/19

**Fig. 16f** SECOND METAL FILM (SILVER ALLOY) DEPOSITION



**Fig. 16g** PATTERNING OF SECOND METAL FILM









17/19

**Fig. 17h**



**Fig. 17i**



PATTERNING OF ITO





18/19

*Fig. 18*



*Fig. 19*



19/19




Fig. 20